


GRIND # DP 117KHD



Valve timing is checked with zero valve lash @ 0.020 inches of valve lift

Above data for checking only! Numbers on rocker arm motors may vary due to rocker arm ratio or multiple valve jobs.

	Intake	Exhaust
Lift @ Cam	<u>.345</u>	<u>.325</u>
Duration	<u>277</u>	<u>294</u>
Lobe Center	<u>106.5</u>	<u>110</u>
Valve Lash	<u>.005"</u>	<u>.005"</u>